

GUIDE TO THREAD PENETRATION



For both Nuts and Lock nuts



Excessive thread penetration.
Bolts too long.



Ideal result is for the thread to
penetrate from 1½ to 2 turns
past the nut.

